Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Ulmer/Pe	rkins	Date(s):	Date(s): Aug 12-14, 2019				
0	Laterman	atain Can Canana	LINIA/ODID.	Idaha Falla				
Company/Owner:	Intermou	ntain Gas Company	Unit/OPID:	Idaho Falls				
Inspection Type & Time (1	day, 0.5 day)	To	otal Inspection Da	ys: 14				
Standard: 12 Construction:	2 Training:	(T)(D) Integrity Manage	ment: Inciden	t:				
M/M: Follow-up:	OQ:	Damage Prevention	: D&A:					
Inspection Summary								
Audit consisted of inspecting field installed equipment and operator qualification for the Idaho Falls, Idaho inspection units. Records and procedures for all Idaho Intermountain Gas Units were inspected in February 2019 at the Intermountain Gas Company (IGC) headquarters in Boise, Idaho.								
Aug 9, 2019: (2 Standard Prep) Prepared for the field audit of Intermountain Gas Company's natural gas distribution pipeline for the Idaho Falls, Idaho inspection unit. Reviewed operators operations/maintenance manuals, emergency manuals, operator qualification procedures and the previous years audit results. Prepared PHMSA Form 2 IA question set and IPUC Forms and worksheets for the inspection.								
Aug 11, 2019: (2 Standard travel) Traveled over to Idaho Falls, ID to conduct the field audit.								
Aug 12-14, 2019: (6 Standard) Met with IGC company representatives in the Idaho Falls district office for in-brief and to begin field audit.								
Regulator Stations 70004, 70005, 70008, 70009, 70010, 70011, 70012, 70013, 70014, 70015, 70016, 70017, 70018, 70019, 70020, 70021, 70032, 70035, 70036, 70037, 70040, 70041, 70043, 70044, 70048, 70050, 70051, 70053, 70054, 70056, 70057, 70058, 70059, 70060, 70062, 70063, 70064 and 70145 were inspected for proper operating parameters, regulator lock-up, relief device operation, cathodic protection pipe-to-soil readings, pipe-to-soil interface wrap protection, station warning signs and right-of-way clearances.								
Eight casing-to-carrier isolation checks, five cathodic protection rectifiers, eight pipeline patrols, and eight emergency isolation valves were checked for proper operation and found to be operating properly.								
An IPUC Form 3 (exit interview) was performed following the district inspection with Kelley Gorringe (Pipeline Safety Specialist) of Intermountain Gas Company.								
Observations: Reg Stations: 70009, 70017, 7 Reg Stations: 70021 (primary) cleaned needles on the spot. Reg Stations: 70035 and 7004 C2Cs 72900201, 74102701 an	, 70059 (primary) fa 4 were found leakin d 74109407 had low	iled to lock-up. Meter i g.		aphragms and				

Idaho PUC Pipeline Safety Inspection Summary

Aug 15, 2019: (2 Construction	1)									
Observed the crew line locating old Aldyl-A, trenching with a trenching machine for ¾" service line, potholing in preparation for the bore, boring the ¾ service line, bedding, and setting riser. They excavated the 2" PE they had installed prior to our inspection. Watched them bore under the main road to their tie-in location.										
Areas observed during this project were: Trenching, Boring, Potholing, Line Locating and Bedding.										
Aug 16, 2019: (2 Standard Por Completed forms and typed r										
Attached: IPUC Form 1, Inspection Sumi IPUC Form 3, Exit Interview IPUC Field Equipment Status N PHMSA IA Question Set, Field	,	ed but in IA database)								
Corrective Action Required:		Yes X	No							
Follow-up Required:	by (date): Noy 201		No							
Inspector (Lead):	War HALL	Dat	e: Aug ((a 2	2019					
Reviewer:	10-0- 1-0 100	Dat		4, 0	, - ,					
	I control of the cont									